	Туре	L #	Hits	Search Text	DBs	Time Stamp
1	BRS	L1	37	(lens adj3 barrel) and (screw same washer) and	USPAT; EPO; JPO; Derwen t; IBM TDB	
2	BRS	L7	0	((screw\$ same washer\$) same	USPAT; EPO; JPO; Derwen t; IBM TDB	10:04
3	BRS	L13	33	((screw same washer) same	USPAT; EPO; JPO; Derwen t; IBM TDB	1
4	BRS	L19	43	(lens near5 barrel) and (screw same washer) and coupling	USPAT; EPO; JPO; Derwen t; IBM TDB	: 1
5	BRS	L25	443	(screw\$ same washer\$) same reinforce\$	USPAT; EPO; JPO; Derwen t; IBM TDB	2001/02/23 10:19
6	BRS	L31	0	19 and 25	USPAT; EPO; JPO; Derwen t; IBM	;

	Comments	Error Definition	Err ors
1			О
2		Truncation Overflow. Return string from Server is: 5`0`0`SCR	1
3			0
4			О
5		Truncation Overflow. Return string from Server is: 5`0`0`SCR	1
6			0

Page 2 (TNguyen7, 02/23/2001, EAST Version: 1.01.0015)

	Туре	L #	Hits	Search Text	DBs	Time Stamp
7	BRS	L37	4		USPAT; EPO; JPO; Derwen t; IBM TDB	
8	BRS	L43			USPAT; EPO; JPO; Derwen t; IBM TDB	2001/02/23 10:21
9	BRS	L49	О	25 and (lens near5 barrel)	USPAT; EPO; JPO; Derwer t; IBM	2001/02/23
10	BRS	L55	140	(lens near5 barrel) and (screw same washer)	•	2001/02/23

	Comments	Error Definition	Err ors
7			Ο
8			О
9			О
10	)		0